

*Heavy Commercial Vehicles*

| Persons to be contacted for bulletin: | Service Manager | Warranty Manager | Spare Part Manager | Chief Technician | Service Advisor | BMIS |
|---------------------------------------|-----------------|------------------|--------------------|------------------|-----------------|------|
|                                       | ✓               | ✓                | ✓                  | ✓                | ✓               | ✓    |

|                |   |
|----------------|---|
| <b>Subject</b> | Gen 2.0 OFCA Removal and Installation   |
| <b>Model</b>   | All Gen 2.0 Vehicles  |
| <b>Summary</b> | The oil cooler (OFCA) in Gen 2.0 vehicles is longer in the Y direction compared to Gen 1,5 and Gen 1.0. Thus, removing or installing the oil cooler requires extra effort and time. The service instructions and labor codes are provided in the TSB. |

*Labor Codes*

| Labor Code      | Labor  | Time (h)    |
|-----------------|--|-------------|
| F4V44 6C732GEN2 | Gen 2.0 Engine Oil Cooler R/I  | 1           |
| F4V45 M97B44    | Coolant Drain & Fill (Radiator Drain Tap R/I Included.)                          | 0,4         |
| F4V44 6744GEN2  | Gen2 Engine Oil Filter Replacement (Engine Oil Change NOT Inc.)                  | 0,2         |
| F4V44 6K682GEN2 | Gen2 Turbocharger R/I (Heat Shield & Oil and Coolant Pipes TC Side R/I Included) | 2,25        |
| F4V44 9K640     | TC Casting Air Pipe R/I  | 0,25        |
| F4V44 CCVHOSES  | CCV Hoses R/I  | 0,15        |
| F4V44 6K770     | Intercooler Air Hose (Hot Side) R/I  | 0,2         |
| F4V53 9F464GEN2 | Gen2 EGR Cooler R/I (Air & Coolant Line EGR Cooler Side Dismantle Inc.)          | 1           |
| F4V44 9M449GEN2 | Gen2 EGR Heat Shield R/I   | 0,2         |
| F4V44 9T540     | 7th Injector R/I (Injector Side Fuel Line Included.)                             | 0,4         |
| F4V44 2K169     | Exhaust Back Pressure Valve R/I  | 0,4         |
| F2V86 CABTILT   | Cab Tilting  | 0,1         |
| <b>TOTAL</b>    |  | <b>6,55</b> |

*Affected Parts*

|             |              |           |
|-------------|--------------|-----------|
| <b>SC46</b> | <b>6C732</b> | <b>A*</b> |
| <b>SC46</b> | <b>6C732</b> | <b>B*</b> |

*Required Parts*


| Part Name                     | Part Number    | Quantity |
|-------------------------------|----------------|----------|
| Oil Fill Plug                 | SC46-6B607-A   | 1        |
| Oil Fill Plug Washer          | SC46-4999-A    | 1        |
| Turbo Oil Drain Pipe Gasket   | GC46-6N652-B   | 2        |
| Turbo Oil Feed Pipe           | SC46-6K679-A*  | 1        |
| Turbocharger- Manifold Gasket | SC46-9L461-A*  | 1        |
| Turbocharger – EBPV Gasket    | SC46-9L462-A*  | 2        |
| EBPV Clamp                    | SC46-6C840-A   | 2        |
| Turbochager-Manifold Bolt     | GC46-9454-B*   | 4        |
| OFCA Gasket                   | GC46-6N782-A   | 1        |
| EGR Cooler Strap              | SC46 -9J496-AA | 2        |

**Subject**


Due to narrow space between the chasis and the oil filter housing in Gen 2.0 vehicles, the OFCA removal requires extra steps compared to the previous engines. On Gen 1,5 and Gen 1.0, Turbo unit removal was sufficient for OFCA removal. For Gen 2.0 vehicles, the EGR Cooler and the Exhaust Downpipe including Exhaust Back Pressure Valve has to be removed in order to service the oil cooler. You can use the Gen 2.0 specific labor code F4V44 6C732GEN2 with the complete recipe provided above for the labor expenses. The steps to follow for Gen 2.0 OFCA R/I are described below:

**Service Instructions**


1. Drain the coolant from the vehicle and tilt the cabin
2. Remove the Turbo Oil Feed Pipe (SC46-6K679-A\*) and Engine Charge Oil Drain Pipe (SC46-6K677-A\*)




3. Disconnect the Turbo connections and remove the Turbo Unit




4. Disconnect and remove the EGR cooler and the Exhaust Downpipe including the Exhaust Back Pressure Valve which is positioned on the downpipe.



- Loosen the oil filter plug until oil starts to drain beneath the filter. Wait for the oil drain to be complete (approximately 1,5 L) and remove the filter.




- Remove the oil cooler using the space created via Turbo, EGR Cooler and Downpipe removal.




**Note:** Please see Attachement 1 – Gen 2.0 OFCA Removal for video illustration of the oil cooler removal.

### Re-Assembly


- Place the OFCA Gasqet (6N782) on the back surface of the oil cooler




2. Place two bolts on the corners.



3. Place the OFCA on the correct position with the bolts corresponding to their seats on the block




4. Place the remaining bolts and torque according to the instructions below:






5. Install the EGR Cooler and EGR Cooler inlet & outlet pipes




6. Install the Turbo Unit, the EBPV and the Exhaust Downpipe



ASSEMBLY PROCEDURE



- 1- EBPV IS FITTED TO THE TURBO WITH THE GASKET AND CLAMP. ENSURE ALIGNMENT PIN ON THE EBPV MATCHES THE HOLE ON THE TURBO FLANGE AND THE GASKET
- 2- EBPV CLAMP BOLT IS TORQUED TO 12 ± 1 Nm.
- 3- THEN DOWNPIPE IS FITTED TO THE EBPV WITH THE GASKET AND CLAMP. AFTER 10 MINUTES, RE-TORQUE TO 12 NM ± 1
- 4- DOWNPIPE CLAMP BOLT IS TORQUED TO 12 ± 1 Nm.

7. Install the Turbo Oil Feed Pipe and Oil Drain Pipe




Below is the OFCA Complexity Table for Gen 2.0 Vehicles

| GEN2 OFCA Complexity Table    |      |      |     |                               |      |      |     |
|-------------------------------|------|------|-----|-------------------------------|------|------|-----|
| OFCA w OTCV - SC46-6C732-A    |      |      |     | OFCA w/o OTCV - SC46-6C732-B  |      |      |     |
| 12.7L 510PS                   | SC46 | 6007 | AA  | 12.7L 510PS - 450PS E6        | SC46 | 6007 | ALA |
| 12.7L 510PS PTO               | SC46 | 6007 | CA  | 12.7L 450PS E6 PTO            | SC46 | 6007 | AMA |
| 12.7L 510PS INT               | SC46 | 6007 | EA  | 12.7L 510PS - 450PS E6 INT    | SC46 | 6007 | ANA |
| 12.7L 510PS PTO INT           | SC46 | 6007 | GA  | 12.7L 450PS E6 PTO INT        | SC46 | 6007 | APA |
| 12.7L 510PS CP                | SC46 | 6007 | JA  | 12.7L 510PS - 450PS E6 CP     | SC46 | 6007 | CLA |
| 12.7L 510PS PTO CP            | SC46 | 6007 | LA  | 12.7L 450PS E6 PTO CP         | SC46 | 6007 | CMA |
| 12.7L 510PS INT CP            | SC46 | 6007 | NA  | 12.7L 510PS - 450PS E6 INT CP | SC46 | 6007 | CNA |
| 12.7L 510PS PTO INT CP        | SC46 | 6007 | RA  | 12.7L 450PS E6 PTO INT CP     | SC46 | 6007 | CPA |
| 12.7L 420PS - 450PS           | SC46 | 6007 | ATA | 12.7L 450PS E6 AC             | SC46 | 6007 | AGA |
| 12.7L 420PS - 450PS INT       | SC46 | 6007 | AVA | 12.7L 450PS E6 AC PTO         | SC46 | 6007 | AHA |
| 12.7L 420PS - 450PS INT PTO   | SC46 | 6007 | AYA | 12.7L 450PS E6 AC INT         | SC46 | 6007 | AJA |
| 12.7L 420PS -450PS CP         | SC46 | 6007 | CTA | 12.7L 450PS E6 AC PTO INT     | SC46 | 6007 | AKA |
| 12.7L 420PS - 450PS INT CP    | SC46 | 6007 | CVA | 12.7L 450PS E6 AC CP          | SC46 | 6007 | CGA |
| 12.7L 420PS- 450PS INT PTO CP | SC46 | 6007 | CYA | 12.7L 450PS E6 AC PTO CP      | SC46 | 6007 | CHA |
| 12.7L 420PS PTO               | SC46 | 6007 | ACA | 12.7L 450PS E6 AC INT CP      | SC46 | 6007 | CJA |
| 12.7L 420PS PTO CP            | SC46 | 6007 | CCA | 12.7L 450PS E6 AC PTO INT CP  | SC46 | 6007 | CKA |



## During Re-Assembly:

- The parts in the “Required Parts” list at the beginning of this bulletin should be replaced with new ones.
- Check the bolts before re-assembly. Replace damaged bolts.
- In case of OFCA replacement, LC46-9D290-A\* Oil Pressure Sensor & GC46-9T305-A\* Oil Temperature Sensor and SC46-12A648-A\* Coolant Pressure Sensor can be carried from the used OFCA, avoid damaging the sensors during repair.



Best Regards  
Ford Trucks Service Engineering

Kişiyi/Departmana Özel | Person/Department-Specific