

SERVICE PROCEDURE

REFERENCE: FSA 202601

DATE: 06.05.2026

SUBJECT: Air Filter Clogging Warning V2

FSA TYPE: Next Service Visit

Introduction

In F-MAX and F-LINE vehicles due to unnecessary warning message on cluster, air clogging sensors must be replaced.

Service Implementation:


Labour Code	Labour Name	Duration (hr)
F4V55 9N622	Air Filter Clogging Sensor Replacement	0,25 hr

Part Usage:

Part Code	Part Name	Quantity
DC46 9N622 AA	Air Filter Clogging Sensor	1

Service Implementation :

The air clogging sensors with part numbers "RC46-9N622-AB" must be replaced with "DC46 9N622 AA" and tightened clockwise by hand after threading.



Best Regards,
Ford Trucks Service Engineering