

SERVICE INSTRUCTIONS

REFERENCE: FSA202217

DATE: 13.01.2023

SUBJECT: Installation of ADR Harness Cap

FSA TYPE: Customer Notification

Introduction

FSA202217: In Specified of F-MAX vehicles, ADR Harness CAP will be installed.

Labour:


Labour	Labour Name	Duration
31C023 B	Installation of ADR Harness Cap	0,2

Parts:

Part Number	Part Description	Usage
PC46-14293-EA	ADR Harness Cap	1

Service Application

In vehicles with H625 ADR, the 7-pin socket (blue one) shown in the left picture below should be connected as it seen right picture below.



Ford Trucks Service Engineering
Ford Otosan A.Ş