

SERVICE INSTRUCTIONS

REFERENCE:FSA202206

DATE: 17.05.2022

SUBJECT: Replacement of VIN Plate for GCC Market

FSA TYPE: Recall

Introduction

FSA202206: In Specified of VIN List, VIN plates will be changed due to incorrect spec information.

Labour:

Labour	Labour Name	Duration
16C116 Q	Replacement of VIN Plate	0,2

Parts:

Part Number	Part Description	Quantity
JC46-D01631-AC	VIN Plate	1
W525100 S437	Rivet	2

Important Note: Part Orders were placed from the headquarters for part/stock management.

Service Application

1- Please cut the rivets by using a screwdriver to remove VIN plate as shown below picture.



SERVICE INSTRUCTIONS

REFERENCE:FSA202206

DATE: 17.05.2022

SUBJECT: Replacement of VIN Plate for GCC Market

FSA TYPE: Recall

2- The VIN plate will be installed to the left side (when stand and look from the front of the vehicle) with 2 rivets.



Ford Trucks Service Engineering
Ford Otosan A.Ş