

SERVICE INSTRUCTIONS

REFERENCE: GAR202103

DATE: 17.04.2021

SUBJECT: Turbocharger Oil Pipe Control

FSA TYPE: Next Service Visit

Introduction

GAR202103: In Specified of vehicles, Turbocharger Oil Pipe control will be applied. VIN list is given in EW System as GAR202103

Labour:

Labour	Labour Name	Duration
21C115 H	Turbocharger Oil Pipe Control	0,4 hours

Service Application

1- Oil leakage should be checked on the pipe seating surface.



SERVICE INSTRUCTIONS

REFERENCE: GAR202103

DATE: 17.04.2021

SUBJECT: Turbocharger Oil Pipe Control

FSA TYPE: Next Service Visit

2- The pipe should be pulled up



3- If you pull the pipe upwards, if there is no dislodgement, make sure that it is fit well by pushing it in the right direction.



If it displaces when pulled up, contact service engineering without any application.