

Heavy Duty Vehicle

Information bulletin to be circulated to:	Service Manager	Warranty Manager	Parts Manager	Master Technician	Service Consultant	BMIS
	✓.	✓.	✓.	✓.	✓.	✓.

Subject	OFCA Bypass Control on 12,7L Ecotorq Engines
Variant	H476MCA & H566MCA & F-MAX vehicles with 12.7L Ecotorq Engine
Abstract	OFCA Bypass Valve must be checked during maintenance of 12.7L Ecotorq Engine.

Components

Labour Code	Labour Description	Time
21C002 C	OFCA Bypass Valve Control	0,1

OFCA Bypass Valve Control

OFCA Bypass Valve must be check during maintenance of engine. **Take photos like below and attach these in claim card** in order to inform related teams about situation.

***Failed Bypass Valve******Bypass Valve without Problem***

* Please follow “**USM-ENHCV-1322-OFCA Bypass Valve Control**” If observe problem on the valve.

** **Please be sure photos are attached in warranty claim** to get approval for the labour code **21C002 C**.

Best Regards,
Ford Trucks Service Engineering