

**Heavy Commercial Vehicles**

People to receive the newsletter:	Service Manager	Warranty Manager	Spare Parts Manager	Chief Technician	Service Advisor	BMIS
	✓	✓	✓	✓	✓	✓

<b>Subject</b>	TSB-Lower mattres topper is missing
<b>Model</b>	F-Line
<b>Summary</b>	In vehicles without a mattress topper, a mattress topper will be placed on the lower bed.

**Labor (Vehicle): F-Max**

Labor Code	Labor Name	Time
F7V03 19H314	Mattress Topper	5 minutes

**Part to be used (Vehicle):**

Part Number	Part Name	Quantity
SC46 19H314-BAZHPK	F-Line Mattress Topper	1

**Service Application****MATTRESS TOPPER ADDITION**

For F-Line vehicles without a mattress, the part numbered SC46 19H314 BAZHPK sent to the dealer will be placed on the lower bed of vehicles with a specified VIN.

These vehicles were originally required to be delivered with a matress, therefore, this part is supplied to fulfill the missing equipment requirement and to ensure vehicle conformity to the intended delivery specifications.

Sincerely yours.

Ford Trucks Service Engineering